

Message

From: Ex. 6 PP / Ex. 7(C)
Sent: 4/16/2020 12:01:24 PM
To: Ex. 6 PP / Ex. 7(C)
CC:
Subject: Fwd: (CAA - FY20-203641-3714) Criminal Tip and/or Complaint - Kentucky
Attachments: Tip_JSON.json; ATT00001.htm

Flag: Follow up

Ex. 6 PP / Ex. 7(C) can you look at this lead to see if we have an interest. Thank you.

Ex. 6 PP / Ex. 7(C)
U.S. EPA-Criminal Investigation Division
Region 4, Knoxville Resident Office
408 N. cedar Bluff Rd., # 202
Knoxville, TN 37923

Ex. 6 PP / Ex. 7(C)

Begin forwarded message:

From: "HQ-Leads_CID@epa.gov" <HQ-Leads_CID@epa.gov>
Date: April 15, 2020 at 9:01:21 PM EDT
To: Ex. 6 PP / Ex. 7(C)
Ex. 6 PP / Ex. 7(C)
Subject: FWD: (CAA - FY20-203641-3714) Criminal Tip and/or Complaint - Kentucky

04/15/2020

SUBJECT: FWD: (CAA - FY20-203641-3714) Criminal Tip and/or Complaint - Kentucky
FROM: HQ-Leads_CID@epa.gov
TO: Ex. 6 PP / Ex. 7(C)
CC:

Tip ID: 203641

This seems like a classic case Ex. 6 PP / Ex. 7(C)

-----Original Message-----

4/15/2020 4:37 PM

HQ LEAD NUMBER: FY20-203641-3714

SUBJECT: Criminal Tip and/or Complaint - Kentucky

FROM: Ex. 6 PP / Ex. 7(C)

TO:

Name:

Ex. 6 PP / Ex. 7(C)

Phone:

Alleged Violator's Name: Shamrock technologies

Alleged Violator's Address: 301 community drive

Alleged Violator's City: Henderson

Alleged Violator's State: Kentucky

Alleged Violator's Zip: 42420

Submitter IP Address:

Ex. 6 PP / Ex. 7(C)

Tip or Complaint: They are running an e-beam to irradiate ppte, without using a scrubber releasing pfoa and HF into the air. They have 3 beams and 3 scrubbers however one scrubber is for the ovens which they have a scrubber good for 600lbs material per load and they bake 1200lbs and use 4 ovens not one like reported.

Violation Still Occurring? Yes

State DEP/DEQ/DEM Notified? No